




Base print or type. (Form designed for use on elite (12-pitch typewriter).)

89476862
 IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C.A.D.0.8.6.5.1.0.0.0.5		Manifest Document No. 911024		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.						
3. Generator's Name and Mailing Address McDonnell Douglas Aircraft Co. 19503 S. Normandie Avenue Torrance, CA 90502						A. State Manifest Document Number 89476862								
						B. State Generator's ID H.A.H.0.3.6.0.0.5.6.9.8								
4. Generator's Phone (213) 533-6677 K. L. Anderson 722 M/S C6-10						C. State Transporter's ID 005434								
5. Transporter 1 Company Name Lutrel Trucking, Inc.						D. Transporter's Phone (805)834-5906								
6. US EPA ID Number C.A.D.0.8.3.0.0.3.6.9.9						E. State Transporter's ID								
7. Transporter 2 Company Name						F. Transporter's Phone								
8. US EPA ID Number						G. State Facility's ID								
9. Designated Facility Name and Site Address USPCI Grassy Mountain Facility U.S. Pollution Control, Inc. 3 Mi.E., 7 Mi.N. Knolls Ex. 41 Clive, Ut. 84074						H. Facility's Phone (801)534-0054								
10. US EPA ID Number U.T.D.9.9.1.3.0.1.7.4.8														
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) a. Waste Corrosive Solid, n.o.s., Corrosive Material UN1759, (D002 & D007)						12. Containers No. Type 0101 DIT		13. Total Quantity 00920		14. Unit Wt/Vol v				
c.										State 611				
										EPA/Other D002D007				
d.										State				
										EPA/Other				
J. Additional Descriptions for Materials Listed Above (Site) Soil contaminated with Chromic Acid from Tank Demo. Sample I.D.# G189-1463-89 Profile # 15189						K. Handling Codes for Wastes Listed Above a. 03, DSP		b.						
						c.		d.						
15. Special Handling Instructions and Additional Information Guide #60. Wear proper protective clothing when handling. Return to GEN. if rejected. 445														
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.														
Printed/Typed Name Kris L. Anderson Agent for M.D.A.C.						Signature 			Month Day Year 011590					
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name Kent Dillard			Signature 			Month Day Year 10115189		
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name			Signature			Month Day Year		
19. Discrepancy Indication Space <div style="text-align: right;">906-297</div>														
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.														
Printed/Typed Name Scott D. Williams						Signature 			Month Day Year 1011161910					

Leave print or type. (Form designed for use on elite (12-pitch typewriter).)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C.A.D.0,8,6,5,1,0,0,0,5		Manifest Document No. 911024		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.													
3. Generator's Name and Mailing Address McDonnell Douglas Aircraft Co. 19503 S. Normandie Avenue Torrance, CA 90502						A. State Manifest Document Number 89476862															
4. Generator's Phone (213) 533-6677 K. L. Anderson 722 M/S C6-10						B. State Generator's ID H.A.H.Q.3,6,0,0,5,6,9,8															
5. Transporter 1 Company Name Lutrel Trucking, Inc.			6. US EPA ID Number C.A.D.0,8,3,0,0,3,6,9,9			C. State Transporter's ID 005434		D. Transporter's Phone (805)834-5986													
7. Transporter 2 Company Name			8. US EPA ID Number			E. State Transporter's ID		F. Transporter's Phone													
9. Designated Facility Name and Site Address USPCI Grassy Mountain Facility U.S. Pollution Control, Inc. 3 Mi.E., 7 Mi.N. Knolls Ex. 41 Clive, Ut. 84074						10. US EPA ID Number U.T.D.9,9,1,3,0,1,7,4,8															
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) a. Waste Corrosive Solid, n.o.s., Corrosive Material UN1759, (D002 & D007).						12. Containers No.		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.									
						0101		DIT		99920		Y		State 611							
														EPA/Other D002D007							
														State							
														EPA/Other							
J. Additional Descriptions for Materials Listed Above (11a) Soil contaminated with Chromic Acid from Tank Demo. Sample I.D.# G489-1463-89 Profile # 15189						K. Handling Codes for Wastes Listed Above a. b. c. d.															
15. Special Handling Instructions and Additional Information Guide #80. Wear proper protective clothing when handling. Return to GEN. if rejected. 445										PROFILE #15189 HAULER 34012. SITE											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.										Printed/Typed Name Kris L. Anderson Agent for M.D.A.C.				Signature <i>[Signature]</i>				Month Day Year 011590			
17. Transporter 1 Acknowledgement of Receipt of Materials										Printed/Typed Name KENT DILLARD				Signature <i>[Signature]</i>				Month Day Year 10115189			
18. Transporter 2 Acknowledgement of Receipt of Materials										Printed/Typed Name				Signature				Month Day Year			
19. Discrepancy Indication Space																					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.										Printed/Typed Name				Signature				Month Day Year			